



# TECHNICAL BULLETIN

8/5/98

---

## DRYERS

### Bulletin No. D101

---

#### GAS IGNITION MODULE AND HIGH VOLTAGE CABLE CHANGE

Information subject to change without notice.

Note: Cissell has added a Cissell Substitution List to the Cissell Parts Price List. The Cissell Substitution List is Section 3 in the Cissell Parts Price List.

Effective January 9, 1998, the dryer models listed below are now using a Ram ignition module in place of the Fenwal ignition module. The Ram ignition module (GA-00765-0) uses a different High Voltage Cable (GA-00803-0) than the Fenwal used.

30 LB  
L28UR30G  
L28US30G

30 LB. STACK  
L28STK30G

50 LB.  
L36URS30G  
L36USS30G  
L36URD30G  
L36USD30G

75 LB.  
L36URS36G  
L36USS36G  
L36URD36G  
L36USD36G

125 LB.  
L125URDG

150 LB.  
L50CD42G

190 LB.  
L50CD48G

**Service parts note:** The Fenwal ignition module (TU13409) is no longer available. The replacement part is K590 (List Price \$111.25). This kit includes the ignition module, high voltage cable, wiring, and instructions.

---

### DRYER OPERATION FEATURES

When we changed to 24 volt controls on dryers (September 1995), we changed the wiring on the manual (2) timer control panel so that it is now necessary to have some time set on the cool down timer before the dryer can be started.

Also a manually resettable thermostat was added to the gas bonnets as an added safety. The dryer will stop if the thermostat is tripped. The dryer cannot be restarted until this thermostat has been reset.